BRUHAT BANGALORE MAHANGARA PALIKE

Inspection Report

1	Name Of Work:	Construction of Second Floor Office for ARO (Yeshwanthpur) at JP Park Swimming Pool Parking area in ward no 17
2	Administration Approval & Date	JC/RRN/AS/2758/2013-14 Dtd: 18.01.2014
3	Technical Sanction Estimate No. & Date	Modified TS: CE/RRN/TS/112/2016-17 Dtd: 28.06.2016
4	Estimate Amount	19,99,000/-
5	Job Code No.	017-14-000063
6	P-Code	P-2434 Development works for Bangalore City
7	Agreement No and Date:	EE/RRND/Agmt/276/13-14 Dtd: 22.02.2014
8	Work order Number & Date	EE/RRND/WO/276/13-14 Dtd: 22.02.2014
9	Contract Amount as per Agreement	Rs. 20,74,988/-
10	Bill Amount	Rs. 20,74,791/-
11	B.R No. & Date	153/16-17 Dtd: 28.09.2016
12	Agency	M/s Vrushabhadri Constructions
13	M.B. Number & Page No. of Measurement records	3923/15-16 Page No 392223 to 392228
14	Date of Inspection	13.09.2017
15	Enclosures 8	Number of photos taken during inspection
16	The above site Location the Conserned person, RRN/PR/414/A/17-18 Inspection Report -re manth of the Items which are Susceptible checked and found	has been Inspected by me along with as per EE (RRND) Letter No EE/ Dated 1-9-2017. The measu- indicated in the MB/XL Sheets, for measurements have been to be satisfactory

13/9/2017

EE (RRN) Division, RR Nagara Zone.

(R. Sathyanarayana)
Inspection Report Officer.

Scanned by CamScanner